

## **Bending shingles -SB 50**



Up to now, 24 work steps were needed to produce shingles.

With the SB 50, you can reduce that to 8 steps. This makes the process 70% faster.

Benefits

- -Manual
- -Mobile
- -Cost-effective
- -Exactly reproducible
- -2 optimal 180° edges in each work step

Bending capacity 500 x 1.0 mm Steel 400 N/mm<sup>2</sup> 500 x 1.5 mm Aluminum 250 N/mm<sup>2</sup> 500 x 0.6 mm VA 600 N/mm<sup>2</sup>

www.schechtl.de